



TEST REPORT

Client: Gabriel
Hjulgagervej 55
Postbox 59
DK-9100 Aalborg
Denmark

Entry No: 96488

Date received: 13/03/2018

Client's Description: Sample of fabric: Cura, Colour: 65104

Test Required: Abrasion and Pilling in accordance with BS EN 14465

Conditioning: In accordance with BS EN ISO 139: 2005 for a minimum of 24 hours at 65+/-4%, Relative Humidity, 20+/-2°C

Date Tests Completed: 10/04/2018

Abrasion Resistance: BS EN ISO 12947-2: 2016^F

The tests were carried out using a pressure of 12 +/- 0.3 kPa
The criterion for judging end point was three threads broken

Specimen 1	180,000 rubs
Specimen 2	170,000 rubs
Specimen 3	160,000 rubs
Specimen 4	170,000 rubs
Overall Result	160,000 rubs

Change in colour after 6,000 rubs: **4-5**

Observation Technique: 10 fold magnification
Type of Fabric: Flat Woven

Pilling: BS EN ISO 12945-2: 2000 Load 415g

	<u>Rating</u>
After 2,000 rubs	5
After 5,000 rubs	4-5

-----End of Document-----

This is hereby certified to be a correct return of the tests made of the items referred to herein

Vivienne Brockbank
Technician
10 April 2018

- ❖ Unless instructed otherwise by the client sample remnants will be disposed of after 28 days.
 - ❖ Tests marked ^N in this certificate are not included in the UKAS Accreditation Schedule for this Laboratory.
 - ❖ Tests marked ^F in this certificate are performed under the Laboratory's Flexible Scope of Accreditation.
 - ❖ Tests marked ^S in this certificate have been subcontracted to another ISO17025 Accredited Laboratory.
 - ❖ Opinions and interpretations expressed herein are outside the scope of UKAS accreditation.
 - ❖ Uncertainty budgets for test methods contained within this report are available on request.
- This Certificate relates only to the sample received and, unless that sample has been drawn by the staff of this laboratory, or its agent, and endorsed accordingly, any application of the result to a bulk quantity or other material is entirely the responsibility of the client.



1104