



Date of Issue: 5/31/2023 Report Number: 23-000498

Revision Number:3

Date Order Received: 02/17/2023

For the Account of: Gabriel A/S

Hjulmagervej 55

9000 Aalborg Denmark

Client's Identification: Renewed Loop Screen

CERTIFICATE OF TESTING

TEST PERFORMED: Resistance to Slippage of Yarns in Woven Fabrics Using a Standard Seam ASTM D4034-92

TEST RESULTS

Specimen	Warp Yarn Slippage (lbf)	Type of Failure	Specimen	Fill Yarn Slippage (lbf)	Type of Failure
1	152.0	SB	1	139.0	SS
2	156.0	SB	2	120.0	SS
3	147.0	SB	3	115.0	SS
4	158.0	SB	4	99.1	SS
5	156.0	SB	5	123.0	SS
Avg. Warp	154.0		Avg. Fill	119.0	

ABBREVIATIONS USED

SB Seam broke before 1/4" slippage - Results should reflect this

SS 1/4" slippage occurred - Note: Actual slippage of yarns is visible

FB Fabric broke before 1/4" slippage - Note: Actual breakage is visible

NOTES

Equipment Used: Tinius Olson H5KT Universal Testing Machine

Seam Description:

Seam TypeStandard LockstitchStitches per Inch 7 ± 0.5 stitches per inch

Needle Used Size 22 NM: 140, 135x17 ball point needle

Thread Nymo EX Bonded Nylon thread; 5x is used for the bobbin and 8x is used for the needle

ACCEPTANCE CRITERIA

A.C.T. Standard Acceptance Criteria
Upholstery 25 lbs. Minimum

CERTIFICATION I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the standard stated above.

Berta Stiver

Authorized Signature Date Order Completed: 02/23/2023