

West Yorkshire Materials Testing Service PO Box 5, Nepshaw Lane South, Morley, Leeds LS27 0QP

Tel: 0113 253 0241 Fax: 0113 252 7029 Materials Testing Manager: D. Brockbank

Client: Gabriel

> Hjulmagervej 55 Postbox 59 DK-9100 Aalborg

Denmark

**Entry No:** 67262-01

Date received: 14/10/2014

Client's Description: Sample of fabric: Art. Soul TFR

**TEST REPORT** 

**Test Required:** Flammability in accordance with BS 5852 ignition source 5

Water soaking in accordance with BS5852:2006 Annex E followed by Line drying **Pre-treatment:** 

**Conditioning:** A minimum of 96 hours at 50 +/- 5% Relative Humidity, 23 +/- 2°C

Method of Test: BS 5852 : 2006 Clause 11 (composites)

Date of Test: 03/11/2014

The following test results relate only to the ignitability of the combination of upholstery composites under the particular conditions of test. They are not intended as a means of assessing the full potential fire hazard of the materials in use.

Ignition Source	Observations	Result
5 (Wood Crib)	Flaming ceased within the specified ten minute period after	PASS
	ignition of the crib and no progressive smouldering occurred on	
	one determination only.	

<b>Note:</b> 50 kg/m3 CMHR foam was used as the filli	ng
---	----

-----End of Page------

This is hereby certified to be a correct return of the tests made of the items referred to herein.





D. Brockbank. Materials Testing Manager 4th November 2014

- Unless instructed otherwise by the client sample remnants will be disposed of
- after 28 days
  Test marked (\*) in this certificate are not included in the UKAS Accreditation Schedule for this Laboratory.
- Opinions and interpretations expressed herein are outside the scope of UKAS
- This Certificate relates only to the sample received and, unless that sample has been drawn by the staff of this laboratory, or its agent, and endorsed accordingly, any application of the result to a bulk quantity or other material is entirely the responsibility of the client.





Client: Gabriel

Hjulmagervej 55 Postbox 59 DK-9100 Aalborg

Denmark

**Entry No:** 67262-01

West Yorkshire Materials Testing Service PO Box 5, Nepshaw Lane South, Morley,

Leeds LS27 0QP

Tel: 0113 253 0241 Fax: 0113 252 7029 Materials Testing Manager: D. Brockbank

## During the tests the following data was recorded: -

_			_
So	 ro	$\sim$	_

Time of ignition (sec)	12	
Time to extinction of flaming (sec)	394	
Time to extinction of smoke (sec)	420	
Time to cover splitting (sec)	29	
Damage on seat width (mm)	159	
Damage on seat length (mm)	227	
Damage on seat depth (mm)	60	
Damage on back width (mm)	279	
Damage on back length (mm)	450	
Damage on back depth (mm)	49	
Melting (Yes or No)	Yes	
Dripping (Yes or No)	No	
Charring (Yes or No)	Yes	

------End of Document-------

This is hereby certified to be a correct return of the tests made of the items referred to herein.





D

D. Brockbank. Materials Testing Manager 4<sup>th</sup> November 2014

- Unless instructed otherwise by the client sample remnants will be disposed of after 28 days
- after 28 days
   Test marked (\*) in this certificate are not included in the UKAS Accreditation Schedule for this Laboratory.
- Opinions and interpretations expressed herein are outside the scope of UKAS accreditation
- This Certificate relates only to the sample received and, unless that sample has been drawn by the staff of this laboratory, or its agent, and endorsed accordingly, any application of the result to a bulk quantity or other material is entirely the responsibility of the client.

